F. A. Reynolds Co. Trumpets

1936 - 1979

#518, c.1936





#8555, c.1945



#8928, c.1946





#10000, c.1946, this is the top model with a Sterling silver bell; an option he copied from the King trumpets



#10225, c.1946, this has a new style vertical engraving



#10267 with Sterling bell and their best engraving yet, c.1946



#12547, c.1947







#12854, c.1947



#13184, c.1947



#13242, c.1947




#19261, Professional model, Sterling bell, c.1949 (author's coll.)



1947: The Ohio brand is merged with Reynolds, the mediumgrade Emporer model starts, and the Regent model is replaced by the Roth.








#19435, c.1949





#20614, Professional model, c.1949



#23808, Professional model, Sterling bell, c.1950



#25550, c.1950




#26xxx, Professional model, c.1951



#27xxx, Contempora model, c.1952







#33231, Contempora model 40L, c.1953



#35822, Emporer model, c.1954





#50617 c.1958

#37712, Emporer model, c.1954



1955: start of Contempora Leonard Smith model

#45394, Contempora model, c.1957



#56089, Argenta model, nickel silver, c.1959 (1st year)



1959: start of Hi-Fi model, medium quality with large bore #66260, Hi-Fi model, c.1962



1961: start of Medalist model replacing Roth at low end #76877, Argenta model, c.1964



1964: production moves to Abilene, TX & Fullerton, CA #230302, Medalist model, c.1967, made in Abilene



#232981, c.1967



1970: Abilene plant closes; all production with Olds at Fullerton





#277569, Ranger model with interchangeable valves, c.1973



#278559, Emperor model, 1973



#280xxx, Medalist model, 1973



#295292, Medalist model, 1974



#300033, Ranger model, 1975



#A18003, Medalist model, 1978



1979: Reynolds is ended